GUIDELINES FOR EVALUATING FOUNDATION PERFORMANCE BY MONITORING

Document no: FPA-SC-12

Developed by: FPA Structural Committee

Committee chairs: Main Committee - Ron Kelm, P.E.

Subcommittee - Nicole Wylie, E.I.T.

Subcommittee: Gary Boyd, Dan Jaggers, Mari Mes,

Dick Peverley, Michael Skoller

Presented by: Nicole Wylie, E.I.T., Forensic Engineers Inc.

Presented to: Foundation Performance Association

Presented on: 11 January 2006

FOUNDATION MONITORING

- 1. Why was it written?
- 2. Who needs it?
- 3. What are the benefits?
- 4. How is it organized?

FOUNDATION PERFORMANCE

FPA-SC-12 Presentation 11 Jan 06

Guidelines for Evaluating Foundation Performance by Monitoring


Table of Contents


1.0	INTRODUCTION	4
2.0	DEFINITIONS	4
3.0	TESTING TO ASSIST IN THE MONITORING PROCESS	6
	3.1 ELEVATION SURVEYS	7
	3.2 GEOTECHNICAL TESTS	7
	3.3 CORING	7
	3.4 PETROGRAPHIC ANALYSIS	
	3.5 GEOPHYSICAL TESTING	8
	3.6 PLUMBING LEAK DETECTION TESTS	8
	3.7 GROUNDWATER MONITORING	8
	3.8 SITE RECONNAISSANCE	8
	3.8.1 Aerial Photos. 3.8.2 Topographic Maps. 3.8.3 Excavation at the Foundation. 3.8.4 Drainage. 3.8.5 Landscaping. 3.8.6 Rainfall Data	9 9 9
4.0	STABILIZATION GUIDELINES	500000000
	4.1 TIME-CHANGE ELEVATION GUIDELINES	10
	4.2 DISTRESS PHENOMENA GUIDELINES	12
5.0	PROCEDURE	13
	5.1 SITE WORK	13
	5.2 DATA EVALUATION	14
6.0	EXAMPLES	14
	6.1 SURVEY ELEVATION PLAN	15
	6.2 MONITORING ELEVATION PLAN	16
	6.3 TIME-CHANGE ELEVATION PLAN	17
	6.4 GRAPH OF PLOT POINTS (ELEVATION VS. TIME)	18
	6.4 GRAPH OF PLOT POINTS (ELEVATION VS. TIME)	


WHAT'S THE DEAL WITH EXPANSIVE SOIL?


It causes:

- Heave
- Subsidence / Shrinkage
- Non-cyclical and Cyclical Movement
- Distress Phenomena










WHAT'S THE DEAL WITH EXPANSIVE SOIL?

It causes:

- Heave
- Subsidence / Shrinkage
- Non-cyclical and Cyclical Movement
- Distress Phenomena

TREES AND SHRINKAGE




Plot from "Tree Root Damage To Buildings," Vol. 1, by P.G. Biddle ISBN 0953308618

WHAT'S THE DEAL WITH EXPANSIVE SOIL?

It causes:


- Heave
- Subsidence / Shrinkage
- Non-cyclical and Cyclical Movement
- Distress Phenomena

GRAPH OF PLOT POINTS VS. TIME:



CYCLICAL MOVEMENT

GRAPH OF PLOT POINTS VS. TIME:



NON-CYCLICAL MOVEMENT

WHAT'S THE DEAL WITH EXPANSIVE SOIL?

It causes:

- Heave
- Subsidence / Shrinkage
- Non-cyclical and Cyclical Movement
- Distress Phenomena

3 TYPES OF PHENOMENA



Architectural



Functional




Structural

ELEVATION SURVEYS



Digital Leveling Systems
Electronic Water Level






GEOTECHNICAL TESTS




Portable Drill Rig






Truck Mounted Drill Rig

GEOPHYSICAL TESTING



GEOPHYSICAL TESTING



PLUMBING LEAK DETECTION TESTING



Tunneling under slab for leak repair



Slab break-out for leak repair

GROUNDWATER MONITORING



Submerged water meter



Water ponding at grade beam / pier

SITE RECONNAISSANCE

- Aerial Photos
- Topographic Maps


Foundation Excavation

Drainage

Landscaping

Rainfall Data

Equipment Tire Tracks




Trees

Aerial Overlay Mid-Development


Nicole Wylie, Forensic Engineers Inc.






Aerial Overlay Pre-Development


- Aerial Photos
- Topographic Maps
- Foundation Excavation
- Drainage
- Landscaping
- Rainfall Data



SITE RECONNAISSANCE

- **Aerial Photos**
- Topographic Maps
- Foundation Excavation
- Drainage
- Landscaping
- Rainfall Data





Excavation Pit

Grade Beam

Pier

- Aerial Photos
- Topographic Maps
- Foundation Excavation
- Drainage
- Landscaping
- Rainfall Data





Poor Drainage Subm



Drains Towards Residence



Submerged / Slimy Water Meter

- Aerial Photos
- Topographic Maps
- Foundation Excavation
- Drainage
- Landscaping
- Rainfall Data






Nicole Wylie, Forensic Engineers Inc.

- Aerial Photos
- Topographic Maps
- Foundation Excavation
- Drainage
- Landscaping
- Rainfall Data...

Rainfall Data

Check out: www.hcoem.org

Average Precipitation at Gauge 470 (Brays Bayou at Belle Park Dr.) and Gauge 2270 (Buffalo Bayou at West Belt)



Monthly Rainfall Plot

Problem: Foundation movement and distress phenomena in new home

Work: Monitoring March 2003 to present

Outcome: Movement cessation predicted within next 12 months

1999: Site cleared, canal filled

Feb 00: Geo report showed PI=41,

soil wetter than plastic limit

Aug 00: Foundation complete

May 01: Closing & Move-In


Jun 01: Owner observed first

distress phenomenon

Mar 02: Engineer of record observes overly wet yard, suspects heave, east-west slab crack is epoxy injected

Oct 02: Engineer returns and finds new slab crack parallel to repair; requests further testing

Mar 03: Forensic Engineers Inc (FEI) were hired




Aerial overlay with north end of house over canal


Mar 03:

FEI used aerial photo overlays to find that house was sited across a canal, a road and mature trees.

185 phenomena observed, some shown at right

Leak test was negative





- •Mature trees + drought = Site desiccated when cleared
- Site still very dry during construction
- First phenomena observed as site began to wet-up in 2001


Mar 03:

FEI Elevation survey shows Maximum Differential Elevation of 2.6"

Contours follow an east-west direction following the rows of felled trees along the canal and road.

FEI confirmed that heave had occurred and recommended monitoring to determine when repairs may be safely made with little risk of reoccurrence.

FEI recommended homeowner start following maintenance procedure outlined in FPA-SC-07.



Adjusted Elevations 31 Mar 03

FPA-SC-12 Presentation 11 Jan 06


Case Study 1:

May 04

Example Survey Elevation Plan at right.

Full Elevation survey conducted every 12 months (figure at right). Note benchmark in backyard.

Limited survey conducted every 3 months with fewer data points (next figure).




FPA-SC-12 Presentation 11 Jan 06

Case Study 1:

Mar 03 - Jun 05:

Time-change Elevations calculated as noted in the figure's legend.


Comparing the contours for the Time-change Elevation Plots showed the high point moving to the right over time.




Mar 03 - Oct 05:

Movement continues, moisture barrier installed

Date	Period (Days)	# New Phenomena	Days / Phenomena
25 May 01	-	Assumed Zero	-
31 Mar 03	673	185	3.6
14 Jul 03	105	5	21.0
14 Oct 03	92	11	7.5
9 Jan 04	87	66	1.3
13 May 04	125	26	4.8
14 Sep 04	123	18	6.8
9 Dec 04	86	29	3.0
29 Mar 05	110	16	6.9
20 Jun 05	83	17	4.8
20 Oct 05	122	18	6.8
TOTALS	1606	391	4.1







May 04 - Oct 05 Plot Point Elevations:

General upward trend with some cyclical movement.

Although A, D, E and F remained level Jul-Oct 05, the weather was extremely dry and a "normal" foundation would have moved

down.





Case Study 1 Conclusion:

Monitoring helped us:

- Understand the type of movement
- Quantify movement and distress phenomena
- Explain the cause and remedy to the owner
- Take appropriate corrective action (moisture barriers)
- Predict movement's end

Problem: Foundation movement and distress phenomena in 1960s home

Work: Diagnosis in June 2003, monitoring began April 2005

Outcome: Foundation has rebounded, slight movement continues

4 bedroom house, built 1963


Piers installed along front left side prior to purchase in late 90s

PI=60-70% (USDA)

Hump running N-S through Den

Extensive distress phenomena

Forensic Engineers Inc's Adjusted Elevation Survey showed 4.0" out-of-level in June 2003, low at Den/Patio.




Adjusted Elevations Recorded June 2003

Comparing FEI's June 2003 survey to a June 2002 survey showed the Patio/Den/Bedroom 2 area had dropped relative to the rest of the residence, and overall change of 1.5" in one year.

22" oak in backyard was blamed; FEI diagnosed subsidence/shrinkage and recommended heavy pruning or removal of 22" oak.

FEI also recommended homeowner correct drainage issues and start following maintenance procedure outlined in FPA-SC-07.




Time-change Elevations
June 2002 to June 2003

22" oak felled Fall 2003

Owner called FEI out in 2005 to access whether the foundation had "rebounded".

Remarkable change - Patio/Den/Bedroom 2 area lifted significantly after felling the tree 18 months prior.

FEI could not ascertain that movement was complete, and monitoring was necessary.




Adjusted Elevations Recorded 14 Apr 05

14 Oct 05 Adjusted Elevation Survey showed 3.0" out-of-level; Compare to 4.0" prior to felling oak tree.

Low point moved from Den/Patio interface to Den/Living Room interface, ~20'.

Recommended further monitoring and heavy pruning of front yard oak.




Adjusted Elevations Recorded 14 Oct 05

Contours on Time-change Elevation Survey tell the story.

Leveling may not be necessary if trend continues.

Too much movement over sixmonth period to advise repair. Owner requests continued monitoring.



Time-change Elevations
19 Jun 03 to 14 Oct 05

Case Study 2 Conclusion:

Monitoring helped us:

- Ascertain that tree removal was correct repair
- Take further corrective action (heavy pruning of front trees) to prevent additional distress
- Understand the direction of movement
- Document the quantity of movement
- Predict movement's end

FOUNDATION PERFORMANCE ASSOCIATION

QUESTIONS?

Download "Guidelines for Evaluating Foundation Movement by Monitoring" at:

http://www.foundationperformance.org/committee papers.cfm